

## 445 - Piper

Piper Customer Services  
Piper Aircraft Corporation  
Lock Haven, Pennsylvania, U.S.A.

**Date:**

April 21, 1965

**TO:**

Distributors, Dealers, Certified Service Centers and Owners

**SUBJECT:**

Installation of Nose Gear Drag Link Clevis Reinforcement Bracket

**MODELS AFFECTED:**

PA-24 and PA-24-250 Comanches, Serial Nos. 24-1 to 24-922 incl., 24-924 to 24-3225 incl.

**COMPLIANCE DATE:**

Prior to but not later than next 100 hour inspection.

This Service Letter is to advise that Kit No. 756 911 consisting of a nose gear drag link clevis reinforcement bracket and necessary hardware is available for installation on the aircraft indicated by the above serial numbers.

It is requested that the reinforcement bracket, which is applicable to clevises, part numbers 20859-03 (HT), 20859-02, or 20859-00, be installed to derive the benefit of the additional support. See sketch below this Service Letter.

**NOTE:**

Compliance with this Service Letter is not required on aircraft that have had Kit Number 754 429 installed in service.

**NOTES:**

1. Remove present clevis retainer plate and discard.
2. Enlarge two existing rivet holes to .189/.191 C'SK' 1000 x .378.

SKETCH